


Piston crown with heavy deposit build-up.
Piston crown after service.



Throttle plate with Heavy deposit build-up.

Throttle plate after service.

Utilizing specialized tools, one of our skilled technicians will immediately:



Fouled fuel injector produces irregular spray pattern, Clean fuel injector displays proper spray pattern.

- ³⁵/₁₇ Clean fuel injectors
- ³⁵/₁₇ Clean throttle body
- ³⁵/₁₇ Clean plenum and air intake system.
- ³⁵/₁₇ Clean intake valves and ports.
- ³⁵/₁₇ Remove combustion chamber deposits.

Our Fuel/Air Induction Service will

- ✓ Improve drivability
- ✓ Alleviate surge, hesitation, hard starting.
- ✓ Reduce emissions.
- ✓ Restore horsepower.
- ✓ Clean fuel injectors.
- ✓ Lower fuel cost.
- ✓ Smoother Idle.



Intake valve with heavy deposit build-up.
Intake valve after service.

Recommended service interval:
15,000 miles